# SAFETY DATA SHEET



Section 1. Identification		
Product name	: Tower Mortar & Stucco Repair Beige	
Product code	: TS-00242 (formulation Number 11925T)	
Other means of identification	: Caulk, Sealant	
Product type	: Paste	
Relevant identified uses of	the substance or mixture and uses advised against	
Product use	: Consumer applications, Professional applications.	
Use of the substance/ mixture	: Caulking, Sealing	
Uses advised against	: Not applicable.	
Supplier	: Tower Sealants 2095 Memorial Park Road Gainesville, GA 30504	
Emergency telephone number	: Chemtrec: 1-800-424-9300	
Technical Phone Number	: 1-770-535-8782 (8:00 am to 5:00 pm EST)	

# Section 2. Hazards identification

OSHA/HCS status	: This material is considered hazardous by the OSHA Hazard Communication Standard (29 CFR 1910.1200).
Classification of the substance or mixture	: CARCINOGENICITY - Category 1A SPECIFIC TARGET ORGAN TOXICITY (REPEATED EXPOSURE) - Category 2
	Percentage of the mixture consisting of ingredient(s) of unknown toxicity: 63%
GHS label elements	
Hazard pictograms	
Signal word	: Danger
Hazard statements	: May cause eye irritation
	: May cause cancer
	: May cause genetic defects
	: May cause damage to organs through prolonged exposure.

ER NTS

SEA

Product name Tower Mortar & Stucco Repair

### Section 2. Hazards identification

#### Precautionary statements

General	<ul> <li>Read label before use. Keep out of reach of children. If medical advice is needed, have product container or label at hand.</li> </ul>	
Prevention	: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Do not breathe dust.	
Response	: Get medical attention if you feel unwell. IF exposed or concerned: Get medical attention.	
Storage	: Store locked up.	
Disposal	: Dispose of contents and container in accordance with all local, regional, national and international regulations.	
Supplemental label elements Hazards not otherwise	Sanding and grinding dusts may be harmful if inhaled. This product contains Crystalline Silica which can cause lung cancer or silicosis. The risk of cancer depends on the duration and level of exposure to dust from sanding surfaces or mist from spray applications. Since this product is not meant to be sanded or sprayed, risk of exposure is considered low. Avoid contact with skin and clothing. Wash thoroughly after handling. Emits toxic fumes when heated.	
classified	: Prolonged or repeated contact may dry skin and cause irritation.	

### Section 3. Composition/information on ingredients

Substance/mixture	: Mixture
Product name	: FORMULATION 11250

Ingredient name	%	CAS number
Limestone	10 - 30	1317-65-3
White mineral oil (petroleum)	1 - 5	8042-47-5
Ethylene Glycol	0.5 - 1.5	107-21-1
Titanium Dioxide	0.5 - 1.5	13463-67-7
Mineral Spirits	0.5 - 1.5	8052-41-3
Crystalline Silica, respirable powder (<10 microns)	0.1 - 1	14808-60-7

SUB codes represent substances without registered CAS Numbers.

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

### Section 4. First aid measures

If ingestion, irritation, any type of overexposure or symptoms of overexposure occur during or persists after use of this product, contact a POISON CONTROL CENTER, EMERGENCY ROOM OR PHYSICIAN immediately; have Safety Data Sheet information available. Never give anything by mouth to an unconscious or convulsing person. Description of necessary first aid measures

Eye contact

: Check for and remove any contact lenses. Immediately flush eyes with running water for at least 15 minutes, keeping eyelids open. Seek immediate medical attention.

Product name Tower Mortar & Stucco Repair

Section 4. First a	id measures
Inhalation	: Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.
Skin contact	: Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.
Ingestion	: If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.
Most important symptoms/	effects, acute and delayed
Potential acute health effe	<u>cts</u>
Eye contact	: Direct contact may cause slight to moderate irritation.
Inhalation	: May cause slight irritation to respiratory passages – headache – dizziness.
Skin contact	: May cause allergic skin reactions and / or central nervous system depression. May cause skin dryness and irritation.
Ingestion	: Low ingestion hazard in normal use.
Over-exposure signs/sym	<u>otoms</u>
Eye contact	: No specific data.
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation dryness cracking
Ingestion	: No specific data.
Indication of immediate med	ical attention and special treatment needed, if necessary
Notes to physician	: Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

See toxicological information (Section 11)

# Section 5. Fire-fighting measures

	United States	Page: 3/13
Specific hazards arising from the chemical	: This material is harmful to aquatic life. Fire water contaminated with the be contained and prevented from being discharged to any waterway, s	
Unsuitable extinguishing media	: None known.	
Suitable extinguishing media	: Use an extinguishing agent suitable for the surrounding fire.	
Extinguishing media		

Product name Tower Mortar & Stucco Repair

### Section 5. Fire-fighting measures

Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon dioxide carbon monoxide metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

# Section 6. Accidental release measures

#### Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	: If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	: Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and materials for co	ntainment and cleaning up
Small spill	: Move containers from spill area. Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a HEPA filter and place in a closed, labeled waste container. Dispose of via a licensed waste disposal contractor.
Large spill	: Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a HEPA filter and place in a closed, labeled waste container. Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

# Section 7. Handling and storage

Precautions for safe handling

Product name Tower Mortar & Stucco Repair

# Section 7. Handling and storage

Protective measures	: Put on appropriate personal protective equipment (see Section 8). Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. If during normal use the material presents a respiratory hazard, use only with adequate ventilation or wear appropriate respirator. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse container.
Special precautions	: If this material is part of a multiple component system, read the Safety Data Sheet(s) for the other component or components before blending as the resulting mixture may have the hazards of all of its parts.
Advice on general occupational hygiene	: Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
Conditions for safe storage, including any incompatibilities	: Do not store below the following temperature: 5°C (41°F). Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

# Section 8. Exposure controls/personal protection

#### **Control parameters**

#### **Occupational exposure limits**

Ingredient name	Exposure limits
Limestone	OSHA PEL (United States, 2/2013).
	TWA: 5 mg/m <sup>3</sup> 8 hours. Form: Respirable
	fraction
	TWA: 15 mg/m <sup>3</sup> 8 hours. Form: Total dust
White mineral oil (petroleum)	ACGIH TLV (United States, 6/2013).
	TWA: 5 mg/m <sup>3</sup> 8 hours. Form: Inhalable
	fraction
	OSHA PEL (United States, 2/2013).
	TWA: 5 mg/m <sup>3</sup> 8 hours.
Ethylene Glycol	ACGIH TLV (United States, 6/2013).
	C: 100 mg/m <sup>3</sup> Form: Aerosol
Titanium Dioxide	OSHA PEL (United States, 2/2013).
	TWA: 15 mg/m <sup>3</sup> 8 hours. Form: Total dust
	ACGIH TLV (United States, 6/2013).
	TWA: 10 mg/m <sup>3</sup> 8 hours.
Mineral Spirits	ACGIH TLV (United States, 6/2013).
	TWA: 525 mg/m <sup>3</sup> 8 hours.
	TWA: 100 ppm 8 hours.
	OSHA PEL (United States, 2/2013).
	TWA: 2900 mg/m <sup>3</sup> 8 hours.
	TWA: 500 ppm 8 hours.
Crystalline Silica, respirable powder (<10 microns)	ACGIH TLV (United States, 6/2013).
	United States Page: 5/13

Product name Tower Mortar & Stucco Repair

# Section 8. Exposure controls/personal protection

	TWA: 0.025 mg/m <sup>3</sup> 8 hours. Form: Respirable <b>OSHA PEL Z3 (United States, 2/2013).</b> TWA: 10 MG/M3 / (%SiO2+2) 8 hours. Form: Respirable TWA: 250 MPPCF / (%SiO2+5) 8 hours. Form: Respirable	
Key to abbreviations		

A	<ul> <li>Acceptable Maximum Peak</li> </ul>	S	<ul> <li>Potential skin absorption</li> </ul>
ACGIH	<ul> <li>American Conference of Governmental Industrial Hygienists.</li> </ul>	SR	<ul> <li>Respiratory sensitization</li> </ul>
С	= Ceiling Limit	SS	<ul> <li>Skin sensitization</li> </ul>
F	= Fume	STEL	<ul> <li>Short term Exposure limit values</li> </ul>
IPEL	<ul> <li>Internal Permissible Exposure Limit</li> </ul>	TD	= Total dust
OSHA	<ul> <li>Occupational Safety and Health Administration.</li> </ul>	TLV	= Threshold Limit Value
R	= Respirable	TWA	= Time Weighted Average
_			• •

Z = OSHA 29CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances

#### Consult local authorities for acceptable exposure limits.

Recommended monitoring procedures	this product contains ingredients with exposure limits, personal, tmosphere or biological monitoring may be required to determine	the effectiveness of
	ne ventilation or other control measures and/or the necessity to u rotective equipment. Reference should be made to appropriate r deference to national guidance documents for methods for the de azardous substances will also be required.	monitoring standards.
Appropriate engineering controls	user operations generate dust, fumes, gas, vapor or mist, use p ocal exhaust ventilation or other engineering controls to keep wor irborne contaminants below any recommended or statutory limits	ker exposure to
Environmental exposure controls	missions from ventilation or work process equipment should be oney comply with the requirements of environmental protection leg ases, fume scrubbers, filters or engineering modifications to the ill be necessary to reduce emissions to acceptable levels.	checked to ensure islation. In some
Individual protection measur		
Hygiene measures	Vash hands, forearms and face thoroughly after handling chemic ating, smoking and using the lavatory and at the end of the work ppropriate techniques should be used to remove potentially cont Vash contaminated clothing before reusing. Ensure that eyewas howers are close to the workstation location.	ng period. aminated clothing.
Eye/face protection <u>Skin protection</u>	afety glasses with side shields.	
Hand protection	hemical-resistant, impervious gloves complying with an approve yorn at all times when handling chemical products if a risk assess ecessary. Considering the parameters specified by the glove ma uring use that the gloves are still retaining their protective proper oted that the time to breakthrough for any glove material may be love manufacturers. In the case of mixtures, consisting of severa rotection time of the gloves cannot be accurately estimated.	ment indicates this is anufacturer, check ties. It should be different for different
Gloves		
Body protection	ersonal protective equipment for the body should be selected ba erformed and the risks involved and should be approved by a spo andling this product.	
	United Sta	tes Page: 6/13

Product name Tower Mortar & Stucco Repair

# Section 8. Exposure controls/personal protection

Other skin protection	: Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
<b>Respiratory protection</b>	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

# Section 9. Physical and chemical properties

#### Appearance

Physical state	: Paste
Color	: Beige
Odor	: Mild Acrylic
Odor threshold	: Not available.
рН	: 7.5-8.5
Melting point	: Not available.
Boiling point	: Not available.
Flash point	: Closed cup: >93.33°C (>200°F)
Auto-ignition temperature	: Not available.
Decomposition temperature	: Not available.
Flammability (solid, gas)	: Not available.
Lower and upper explosive (flammable) limits	: Not available.
Evaporation rate	: 0.34 (butyl acetate = 1)
Vapor pressure	: 2.3 kPa (17.2 mm Hg) [room temperature]
Vapor density	: Not available.
Relative density	: 1.16
Density ( lbs / gal )	: 9.68
Solubility	: Soluble in water
Partition coefficient: n- octanol/water	: Not available.
Viscosity	: 15-40 g/s
Volatility	: 35% (v/v), 31% (w/w)
% Solid. (w/w)	: 69

# Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.

**United States** 

Page: 7/13

Product name Tower Mortar & Stucco Repair

# Section 10. Stability and reactivity

products Section 11 Toxic	dioxide, smoke, oxides of nitrogen.
Hazardous decomposition	: Decomposition products may include the following materials: carbon monoxide, carbon
Incompatible materials	<ul> <li>Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.</li> </ul>
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products. Refer to protective measures listed in sections 7 and 8.

### Information on toxicological effects

#### Acute toxicity

Product/ingredient name	Result		Species	Dose	Exposure
White mineral oil (petroleum)	LD50 Oral		Rat	>5000 mg/kg	-
Ethylene Glycol	LD50 Derm	al	Rabbit	9.53 g/kg	-
	LD50 Oral		Rat	4700 mg/kg	-
Titanium Dioxide	LD50 Oral		Rat	>10 g/kg	-
Mineral Spirits	LD50 Oral		Rat	>5 g/kg	-
Conclusion/Summary	: There are	no data a	vailable on the mixture	itself.	
Irritation/Corrosion					
Conclusion/Summary					
Skin	: There are	no data a	vailable on the mixture	e itself.	
Eyes	: There are	no data a	vailable on the mixture	e itself.	
Respiratory	: There are	no data a	vailable on the mixture	itself.	
Sensitization					
Conclusion/Summary					
Skin	: There are	no data a	vailable on the mixture	e itself.	
Respiratory	: There are	no data a	vailable on the mixture	itself.	
<u>Mutagenicity</u>					
Conclusion/Summary	: There are	no data a	vailable on the mixture	e itself.	
<u>Carcinogenicity</u>					
Conclusion/Summary	: There are	no data a	vailable on the mixture	itself.	
<b>Classification</b>					
Product/ingredient name	OSHA	IARC	NTP		
Titanium Dioxide	-	2B	-		
Crystalline Silica, respirable	-	1	Known to be a humar	n carcinogen.	
powder (<10 microns)					

NTP: Known to be a human carcinogen; Reasonably anticipated to be a human carcinogen OSHA: + Not listed/not regulated: - Product name Tower Mortar & Stucco Repair

### Section 11. Toxicological information

#### **Reproductive toxicity**

**Conclusion/Summary** : There are no data available on the mixture itself.

**Teratogenicity** 

**Conclusion/Summary** : There are no data available on the mixture itself.

Specific target organ toxicity (single exposure)

Not available.

#### Specific target organ toxicity (repeated exposure)

Name	Category
Ethylene Glycol	Category 2
Crystalline Silica, respirable powder (<10 microns)	Category 2

```
Target organs
```

: Contains material which causes damage to the following organs: brain. Contains material which may cause damage to the following organs: kidneys, lungs, liver, heart, upper respiratory tract, skin, central nervous system (CNS), eye, lens or cornea, testes.

#### **Aspiration hazard**

Name	Result
	ASPIRATION HAZARD - Category 1 ASPIRATION HAZARD - Category 1

#### Information on the likely routes of exposure

#### Potential acute health effects

Eye contact Inhalation Skin contact Ingestion	<ul> <li>No known significant effects or critical hazards.</li> <li>No known significant effects or critical hazards.</li> <li>Defatting to the skin. May cause skin dryness and irritation.</li> <li>No known significant effects or critical hazards.</li> </ul>
<u>Over-exposure signs/syn</u>	<u>iptoms</u>
Eye contact	: No specific data.
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation dryness cracking
Ingestion	: No specific data.
Delayed and immediate ef	fects and also chronic effects from short and long term exposure
Conclusion/Summary	: There are no data available on the mixture itself. This product contains Crystalline Silica which can cause lung cancer or silicosis. The risk of cancer depends on the duration and level of exposure to dust from sanding surfaces or mist from spray applications. Exposure to component solvent vapor concentrations in excess of the stated occupational exposure limit may result in adverse health effects such as mucous membrane and respiratory system irritation and adverse effects on the kidneys, liver and central nervous system. Symptoms and signs include headache, dizziness, fatigue, muscular weakness, drowsiness and, in extreme cases, loss of consciousness. Solvents may cause some of the above effects by absorption through the skin. There is some evidence that repeated exposure to organic solvent vapors in combination with

United States Page: 9/13

Product name Tower Mortar & Stucco Repair

# Section 11. Toxicological information

Oral	14122.7 mg/kg
Route	ATE value
Acute toxicity estimates	
Numerical measures of toxic	<u>zity</u>
Fertility effects	: No known significant effects or critical hazards.
<b>Developmental effects</b>	: No known significant effects or critical hazards.
Teratogenicity	: No known significant effects or critical hazards.
Mutagenicity	: No known significant effects or critical hazards.
Carcinogenicity	<ul><li>repeated contact can defat the skin and lead to irritation, cracking and/or dermatitis.</li><li>May cause cancer. Risk of cancer depends on duration and level of exposure.</li></ul>
General	: May cause damage to organs through prolonged or repeated exposure. Prolonged or
Potential chronic health effe	
effects Potential delayed effects	: There are no data available on the mixture itself.
Potential immediate	: There are no data available on the mixture itself.
Long term exposure	
effects Potential delayed effects	: There are no data available on the mixture itself.
Short term exposure Potential immediate	: There are no data available on the mixture itself.
	constant loud noise can cause greater hearing loss than expected from exposure to noise alone. Ingestion may cause nausea, diarrhea and vomiting. This takes into account, where known, delayed and immediate effects and also chronic effects of components from short-term and long-term exposure by oral, inhalation and dermal routes of exposure and eye contact.

# Section 12. Ecological information

IOXICITV		- 14			-
	XICITV	СІТ	XI	10	
		<b>UII</b>			-

Product/ingredient name	Result	Species	Exposure
Titanium Dioxide	Acute EC50 100 mg/l Fresh water	Daphnia - Daphnia magna - Neonate	48 hours

#### Persistence and degradability

Not available.

#### **Bioaccumulative potential**

Product/ingredient name	LogP <sub>ow</sub>	BCF	Potential
White mineral oil (petroleum)	>6		high
Ethylene Glycol	-1.36		Iow
Mineral Spirits	3.16 to 7.06		high

#### Mobility in soil

|--|

Product name Tower Mortar & Stucco Repair

### Section 12. Ecological information

Soil/water partition coefficient (K<sub>oc</sub>)

: Not available.

### Section 13. Disposal considerations

**Disposal methods** 

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Disposal should be in accordance with applicable regional, national and local laws and regulations.

Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees. Section 6. Accidental release measures

	DOT	IMDG	IATA
UN number	UN3077	Not regulated.	Not regulated.
UN proper shipping name	ENVIRONMENTALLY HAZARDOUS SUBSTANCE, SOLID, N.O.S. (carbendazim (ISO))	-	-
Transport hazard class (es)	9	-	-
Packing group	111	-	-
Environmental hazards	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.
Product RQ (lbs)	15015	Not applicable.	Not applicable.
RQ substances	(carbendazim (ISO))	Not applicable.	Not applicable.

### 14. Transport information

#### **Additional information**

DOT	<ul> <li>Package sizes shipped in quantities less than the product reportable quantity are not subject to the RQ (reportable quantity) transportation requirements.</li> </ul>
IMDG IATA	<ul><li>None identified.</li><li>None identified.</li></ul>

Product name Tower Mortar & Stucco Repair

### 14. Transport information

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

### Section 15. Regulatory information

United States inventory (TSCA 8b)	: All components are listed or exempted.
Australia inventory (AICS)	: Not determined.
Canada inventory ( DSL )	: All components are listed or exempted.
China inventory (IECSC)	: Not determined.
Europe inventory ( REACH )	: Please contact your supplier for information on the inventory status of this material.
Japan inventory (ENCS)	: Not determined.
Korea inventory (KECI)	: Not determined.
New Zealand ( NZIoC )	: Not determined.
Philippines inventory (PICCS)	: Not determined.
United States	
<u>SARA 302/304</u>	
SARA 304 RQ : No	ot applicable.
Composition/information on ing	redients
No products were found.	
SARA 311/312	

#### <u>SARA 311/312</u>

Classification

: Immediate (acute) health hazard Delayed (chronic) health hazard

#### Composition/information on ingredients

Name	Fire hazard	Sudden release of pressure	Reactive	Immediate (acute) health hazard	Delayed (chronic) health hazard
White mineral oil (petroleum)	No.	No.	No.	Yes.	No.
Ethylene Glycol	No.	No.	No.	Yes.	Yes.
Titanium Dioxide	No.	No.	No.	No.	Yes.
Mineral Spirits	Yes.	No.	No.	Yes.	No.
Crystalline Silica, respirable powder (<10 microns)	No.	No.	No.	No.	Yes.

Pennsylvania (worker and community right to know act): The following components are cited in the Pennsylvania Hazardous Substances List, and are present at levels that require reporting.

Ethylene G	Slycol
------------	--------

107-21-1 <2%

#### <u>SARA 313</u>

Supplier notification	Chemical name	CAS number	Concentration
	: Ethylene Glycol	107-21-1	0.5 - 1.5
		United States	Page: 12/13

Product name Tower Mortar & Stucco Repair

### Section 15. Regulatory information

SARA 313 notifications must not be detached from the SDS and any copying and redistribution of the SDS shall include copying and redistribution of the notice attached to copies of the SDS subsequently redistributed.

California Prop. 65: A WARNING: This product can expose you to chemicals

including Crystalline Silica (respirable powder), and ethylene glycol, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to <u>www.P65Warnings.ca.gov</u>.

### Section 16. Other information

Hazardous Material Information System (U.S.A.) Health : 2 \* Flammability : 1 Physical hazards : 0

(\*) - Chronic effects

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks Although HMIS® ratings are not required on MSDSs under 29 CFR 1910.1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered mark of the National Paint & Coatings Association (NPCA). HMIS® materials may be purchased exclusively from J. J. Keller (800) 327-6868.

The customer is responsible for determining the PPE code for this material.

 National Fire Protection Association (U.S.A.)

 Health
 2
 Flammability
 1
 Instability
 0

 Organization that prepared
 :
 EHS

Key to abbreviations	<ul> <li>ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IBC = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient</li> </ul>
	MARPOL 73/78 = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) UN = United Nations

#### Indicates information that has changed from previously issued version.

#### **Disclaimer**

the MSDS

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by Tower Sealants, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.